

**From:** [Gary Moore](#)  
**To:** [SHalasz@kleinfelder.com](mailto:SHalasz@kleinfelder.com); [rbergner@flash.net](mailto:rbergner@flash.net)  
**Subject:** Fw: Falcon Refinery Butane Tank  
**Date:** 02/17/2010 08:05 AM  
**Attachments:** [butane tank.ppt](#)

---

Stephen:

I appreciate your help. Here is the location of that tank. Let me know if you know anything about it.

Thanks

Gary Moore  
EPA Region 6  
Response and Prevention Branch  
214-665-6609  
[moore.gary@epa.gov](mailto:moore.gary@epa.gov)

----- Forwarded by Gary Moore/R6/USEPA/US on 02/17/2010 08:02 AM -----

### Falcon Refinery Butane Tank

**Christopher Ruhl** to: Gary Moore

02/17/2010  
07:01 AM

Gary-

I have highlighted the butane tank on the attached two slides. The tank is a large horizontal tank that has approximately 80psi according to the pressure gauge on the tank. Based on air monitoring it appears to be leaking from the bottom of the tank where there is a bolted flange. The flange and bolts are heavily corroded.



[butane tank.ppt](#)

The Chris Ruhl  
USEPA Region 6  
Federal On-Scene Coordinator  
(214) 665-7356 office



9566715